FSD Ref.: _ 消防處檔號


A 9392338

FIRE SERVICE (INSTALLATIONS AND EQUIPMENT) REGULATIONS 消防(裝置及設備)規例 (Regulation 9(1)) (第九條 (1) 款) CERTIFICATE OF FIRE SERVICE INSTALLATION AND EQUIPMENT 消防裝置及設備證書

			1H 171 -52	三 及 段 限 超 曹			
Name 向 顧客姓	of Client:		瑞	發置業有限公	司用加加加		
	of Building :		******	na supringa	ncent to their		
Street I	No./Town Lot :DD76	Lot 1573A		oad/Estate Name : 道/屋苑名稱	龍躍頭 /	簡頭村	
Block:	442 MIN SER SER SER	District 分區	:: W	蒙	Area: HK 上香港	K ✓ NT 新界	
	Building 樓宇類型:[]				posite综合 Licensed premi	35121	
	art 1 Annual Inspection 一部 只適用於年标	命車T百 once	ment which is instat	lation 8(b) of Fire Service (Installat	ions and Equipment) Regulations, the own ire service installation or equipment inspect	ner of any fire service installation of	
Code編碼 (1-35)	Type of FSI 裝置類型	Location(s) 位置		on Condition 狀況評述	Completion D. t.	Next Due Date 下次到期日(DD/MM/Y)	
				NIL			
Part 2 第	写二部 Installation / Mo	dification / Repair	/ Inspection	n work 裝置/改裝/	修理/檢查工作		
Code編碼 (1-35)	Type of FSI 裝置類型	Location(s) 位置		rk Carried out 完成之工作內		允许述 Completion Date 完成日期(DD/MM/Y	
5n	os x 5kg DryPowder F.E.	G/F	Ne	ewly Supply	Conforms with FSD requirements	14-August-2024	
	nos x Sand Bucket	G/F	Ne	wly Supply	Conforms with FSD requirements	4-August-2024	
Part 3 第	三部 Defects 損壞事項				Mark and a sel-		
Code编码 (1-35)	Type of FSI 裝置類型	Location(s) 位置	Outstanding Defects 未修缺點		Comment on De	Comment on Defects 缺點評述	
	1 2	1 10		IV 157 WW		1	
				NIL			
		-3.4			H Ha Thi I Cape	. Of the last of t	
				artic rayland do		ENGIA	
time by the D	tify that the above installations/equin in accordance with the Codes of Pre Inspection, Testing and Maintenance irector of Fire Services. Defects are lis	actice for Minimum Fire Ser of Installations and Equipmented in Part 3.	rvice Installations nt published from	and Signature: time 受權人簽署	Ty house	For FSD use only:	
消防處處	·明以上之消防装置及設住 長不時公佈的最低限度。 ·查测試及保養守則的規格	之消防裝置及設備守	"則與裝置	Name : 姓名 FSD/RC No. : 消防處註冊號碼	71.1197	* Q3	
域	書涉及年檢事可 處所當眼處以供 certificate should be displayed at promin	消防處人員3	E 核	Company Name : 公司名稱 Telephone :	MARTEAM ENGINEER	RING LTD Key-in	
251 (Rev. 1/2	for FSD's inspection if any annual n	eintenance work is involved.	काशकदम	聯絡電話	4-August-2024		
** * LACY. 1/L	V2V)			p tta		1 Verified	



Shop A2, 354 Reclamation Street, Mongkok, Kln





Quotation No.:

No.

SK2024 - 3819

To:

1 4. 96388062.

Date

14/8/2021

型號	货品	数量	銀碼	金额
	初筒	7	635.	6245.
	X 解 推動式 放火台	(/	6250-	6 1250-
Part of the Part of the State o	TS 21 75 1 19382338.		4, 200 -	\$ 700
		party states	Probability Suprement of the second	u filolifia dimendiam-no-hadrigi regionale, genegata paragrapa paga paga paga paga paga pag
of the same of the		Newton Statement which the principle recognition where he		

		MACO BECOME THE PROPERTY OF		/
				-(
-,,-;		- American distribution of the Control of the Contr		
			The second secon	
		n year yearnin i dalaishi di munini yardidalaif muuruyuuliya dalaida kabi	Mahadalaplanda,madaqa, gifudhaqayanga, aluquaqayana,	
			Bernesia and the second	
集知:] 1.如需要"FS251消防証書"請楊肇·否則出門後需年檢後3	美" 恭"	A	1. 100
	2. 請出門前確實清楚文件,如違失于本公司無關。	4 75%	金額	4 1691
			訂 金	
	3. 貨物出門 概不退換		結欠	

Shopkeeper

Payment Terms: 現金Cash 易辦事EPS

轉數快 FPS 161531959

存戶Bank-In 支票Cheques

MAKE ALL CHECKS PAYABLE TO: SKCH (GROUP) LIMITED 勝記周維有限公司 銀行BANKER:中國銀行 BOC (HONG KONG) LIMITED 戶口A/C NO.: 012-872-0-014042-2

SKCH (Group) Limited SKCH (Group) Limited SKCH (Group) Limited SKCH (Group) Limited SKCH (Group) Limited


File:TT/N/ST/169/19 II
Photograph of Proposed Fire Services Installation Plan











Proposed Fire Services Installation Plan Lot No.1573 S.A.(Part) in D.D.76 Kau Tan Tusen, Lung Yeuk Tau, North, New Territories

File: TT/N/ST/169/19 II

Date: 17 June 2024



曾家裘測量師有限公司 THOMAS TSANG SURVEYORS LIMITED Surveyors, Property and Management Consultants