

## Figures


Figure 1 Location Plan


Figure 2 Lot Index Plan

- Figure 3 Extract of the Approved Yuen Long OZP No. S/YL/27
- Figure 4 Plan showing the Public Transport Facilities and Public Car Park
- Figure 5 Internal Floor Area Plan 3/F, Tower 1
- Figure 6 Internal Floor Area Plan 7/F, Tower 1



















| UNIT: |   |           |
|-------|---|-----------|
| 701-1 | = | 249.25m2  |
| 701-2 | = | 265.69m2  |
| 701-3 | = | 252.15m2  |
| 701-4 | = | 268.59m2  |
| TOTAL | = | 1035.68m2 |
|       |   |           |

PROPOSED USE: SOCIAL WELFARE FACILITIES (EXCLUDING THOSE INVOLVING RESIDENTIAL CARE)






SEVENTH FLOOR PLAN (TOWER I) (SCALE: 1:200)

## Site Photos

| Photo Plate 1 | Existing Condition of the Application Site |
|---------------|--|
|               | (3/F, Tower 1, One North)                  |
| Photo Plate 2 | Existing Condition of the Application Site |
|               | (7/F, Tower 1, One North)                  |
| Photo Plate 3 | Existing Condition of the Subject Premises |
|               | (Overview of One North)                    |
| Photo Plate 4 | Surrounding Land Uses                      |
| Photo Plate 5 | Surrounding Land Uses - Residential Use    |




Lift lobby of 3/F



Corridor







301-1: Vacant





301-4: Vacant

| Existing Condition of the Application Site (3/F, Tower 1, One North) | Photo Plate 1 |  |
|--|---------------|--|
|--|---------------|--|


THIRD FLOOR PLAN (TOWER I)



301-2: Vacant



Lift lobby of 7/F



Corridor





701-1: Vacant



701-4: Vacant






Existing Condition of the Application Site (7/F, Tower 1, One North) Photo Plate 2







<u>SEVENTH FLOOR PLAN (TOWER I)</u>



## 701-3:Vacant





Tower 1, One North




Entrance and exit of car park at G/F



G/F lobby and the Atrium



Lift connecting B2/F to 2/F




Basement car park



Existing Condition of the Subject Premises (Overview of One North)

Photo Plate 3




Office lobby, Tower 1



Escalator to office lobby










Industrial or I-O Building





5

6



Data Centre and Industrial/I-O Building



Industrial or I-O Building



Surrounding Land Uses

Photo Plate 4



Logistics Centre/Industrial or I-O Building




Open-air car park



Twin Regency



Wang Fu Court





After the Rain

The Spectra

Surrounding Land Uses – Residential Use

Photo Plate 5



The Parcville

5



One Regent Place

